

Qualification of Microsoft Updates

Series	Type	CPU	Windows Embedded Standard 7	Windows 7 Ultimate SP1	Windows Embedded 8.1 Industry	Windows 10 IoT Enterpris 2019 LTSC
SP5000 Series	Modular Type	Atom	KB4578952 KB4580345 KB4580970	N/A	N/A	KB5011267 KB5018542 KB5018419 KB5017263 KB5012170
ES5000 Series	Slim Type	Celeron	N/A	N/A	N/A	KB5013941 KB5013626
PS5000 Series	Modular Type	Core i7	KB4577053 KB4577051 KB4538483 KB4570673 KB4474419 KB4490628	KB2685811 KB4567409 KB4539601 KB4474419 KB4490628	KB4284863 KB4284878	KB4486153 KB5003243 KB5005030 KB5005112
PS5000 Series	Modular Type	Celeron	KB4577053 KB4577051 KB4538483 KB4570673 KB4474419 KB4490628	KB2685811 KB4567409 KB4539601 KB4474419 KB4490628	KB4284863 KB4284878	KB4486153 KB5003243 KB5005030 KB5005112
PS5000 Series	Modular Type	Atom	N/A	N/A	N/A	KB4486153 KB5003243 KB5005030 KB5005112
PS5000 Series	Slim Type	Core i3	KB4577053 KB4577051 KB4538483 KB4570673 KB4474419 KB4490628	KB2685811 KB4567409 KB4539601 KB4474419 KB4490628	KB4284863 KB4284878	KB4486153 KB5003243 KB5005030 KB5005112
PS5000 Series	Slim Type	Atom	KB4577053 KB4577051 KB4538483 KB4570673 KB4474419 KB4490628	KB2685811 KB4567409 KB4539601 KB4474419 KB4490628	KB4284863 KB4284878	KB4486153 KB5003243 KB5005030 KB5005112
PS6000 Series	Modular Type	Core i7	N/A	N/A	N/A	KB4052623 KB5012170 KB5019966 KB5020615
PS6000 Series	Modular Type	Core i5	N/A	N/A	N/A	KB4052623 KB5012170 KB5019966 KB5020615
PS6000 Series	Modular Type	Celeron	N/A	N/A	N/A	KB4052623 KB5012170 KB5019966 KB5020615
PS6000 Series	Modular Type	Core i3	N/A	N/A	N/A	KB4052623 KB5012170 KB5019966 KB5020615

HMI Software	Version	Windows Embedded Standard 7	Windows 7 Ultimate SP1	Windows Embedded 8.1 Industry	Windows 10 IoT Enterpris 2019 LTSC
GP-Pro EX	Ver. 4.09.450	KB4578952 KB4580345 KB4580970 KB4577053 KB4577051 KB4538483 KB4570673 KB4474419 KB4490628	KB2685811 KB4567409 KB4539601 KB4474419 KB4490628	KB4284863 KB4284878	KB5011267 KB5018542 KB5018419 KB5017263 KB4486153 KB5003243 KB5005030 KB5005112 KB4052623 KB5012170 KB5019966 KB5020615
BLUE	3.3 Service Pack 1	N/A	N/A	N/A	KB5011267 KB5018542 KB5018419 KB5017263 KB4486153 KB5003243 KB5005030 KB5005112 KB4052623 KB5012170 KB5019966 KB5020615
BLUE Open Studio	2020 Service Pack 3	N/A	N/A	KB4284863 KB4284878	KB5011267 KB5018542 KB5018419 KB5017263 KB4486153 KB5003243 KB5005030 KB5005112 KB4052623 KB5012170 KB5019966 KB5020615 KB5013941 KB5013626